



A Division of Thiessen Products, Inc.

INSTRUCTION SHEET FOR TOOL NO. 5823

JIMS® No. 5823 FLYWHEEL LOCKING TOOL IS FOR USE ON 2017 - PRESENT MILWAUKEE 8 ENGINES.

Note: Always wear safety glasses or other face and eye protection such as a full face shield. JIMS® is not responsible for damage, injury, or your work. JIMS® cannot be held liable for the quality and safety of your work.

Caution: *Never attempt to start or rotate engine with JIMS® Tool No. 5823 installed. Remove JIMS® Tool No. 5823 after service is completed.*

Instructions:

1. Clean outside of the crankcase position sensor with spray, and blow dry with air prior to removal.
2. Remove crank position sensor following the procedure from the Harley-Davidson® Service Manual.
3. Rotate flywheel into desired position and insert Tool No. **5823** into the crankcase at the crank position sensor location. Insert stock screw and washer, then tighten.

Note: It may be necessary to rotate flywheel to seat Mighty Bite into the notch of flywheel.

4. When service is complete, remove Tool No. **5823** and replace the crank position sensor according to the service manual instructions. Tighten screw to specification from the service manual.



Performance Parts For Harley-Davidson Motorcycles

VISIT US ON THE WEB AT WWW.JIMSUSA.COM

555 DAWSON DRIVE, CAMARILLO, CA 93012 PHONE 805-482-6913 • FAX 805-482-9224



A Division of Thiessen Products, Inc.

INSTRUCTION SHEET FOR TOOL NO. 5823

JIMS® No. 5823 FLYWHEEL LOCKING TOOL IS FOR USE ON 2017 - PRESENT MILWAUKEE 8 ENGINES.

Note: Always wear safety glasses or other face and eye protection such as a full face shield. JIMS® is not responsible for damage, injury, or your work. JIMS® cannot be held liable for the quality and safety of your work.

Caution: *Never attempt to start or rotate engine with JIMS® Tool No. 5823 installed. Remove JIMS® Tool No. 5823 after service is completed.*

Instructions:

1. Clean outside of the crankcase position sensor with spray, and blow dry with air prior to removal.
2. Remove crank position sensor following the procedure from the Harley-Davidson® Service Manual.
3. Rotate flywheel into desired position and insert Tool No. **5823** into the crankcase at the crank position sensor location. Insert stock screw and washer, then tighten.

Note: It may be necessary to rotate flywheel to seat Mighty Bite into the notch of flywheel.

4. When service is complete, remove Tool No. **5823** and replace the crank position sensor according to the service manual instructions. Tighten screw to specification from the service manual.



Performance Parts For Harley-Davidson Motorcycles

VISIT US ON THE WEB AT WWW.JIMSUSA.COM

555 DAWSON DRIVE, CAMARILLO, CA 93012 PHONE 805-482-6913 • FAX 805-482-9224